Course 1: Legacy CNC 101

Module 1: Preparing Your Shop For CNC

1.1: Receiving Your CNC

Lesson 10: Freight Receiving Instructions

- 1. Upon receipt of freight, visually check the delivery for damage. If there is no damage, except freight & sign POD. If there is noticeable damage to freight, <u>DO NOT</u> sign the POD without <u>noting all damage on paperwork.</u>
- 2. Take pictures of all crate damage before uncrating.
- 3. Make every effort to unload the machine from the crate within 48 hours of receipt in case additional damage was missed at delivery. WE HAVE 5 DAYS TO NOTIFY THE CARRIER (carrier tariff rules) OR CLAIMS ARE AUTOMATICALLY DENIED. Take pictures of all machine damage.
- 4. If freight is damaged, please save packaging and e-mail a copy of all documents and photos to cindy@legacywoodworking.com within 48 hours of receipt of freight.
- 5. Freight claim processing can take up to 90 days. Legacy will do everything we can to get your machine up and running as soon as possible.
- 6. Notification of damage must be received within 5 days of freight delivery, or all repair costs will be the customer's responsibility.