

Course 1: Legacy CNC 101  
Module 1: Preparing Your Shop For CNC  
1.1: Receiving Your CNC  
Lesson 4 - CNC Power Requirements

**Rogue 72 Power Requirements (11HP Spindle)**

- 220V Three-Phase Power
- 50 Amp Circuit

**Renegade 5x10 Power Requirements (11HP Spindle)**

1<sup>st</sup> Line

- Machine: 220V Three-Phase Power
- Machine: 30 Amp Circuit

2<sup>nd</sup> Line

- Vacuum: 220V Single-Phase Power
- Vacuum: 30 Amp Circuit

**Maverick 4x8 Power Requirements (6HP Spindle)**

- 220V Single-Phase Power
- 50 Amp Circuit

**Maverick 4x4 Power Requirements (6HP Spindle)**

- 220V Single-Phase Power
- 40 Amp Circuit

**Maverick 3x5 Power Requirements (3HP Spindle)**

- 220V Single-Phase Power
- 30 Amp Circuit