

Course 1: Legacy CNC 101
Module 1: Preparing Your Shop For CNC
1.1: Receiving Your CNC
Lesson 7 - Set Up CAD/CAM Software & Shop Wi-Fi

You will need a dedicated PC computer to design & program parts for the CNC machine. Here are the minimum requirements for the PC computer to run our suggested CAD/CAM software.

- Processor: 2 Ghz Multi-Core X86 or x64 CPU
- Ram: 4 GB
- Disk Space: Minimum of 500GB
- Display: 1024 x 768 graphics display
- Operating System: Windows 10 or 11
- Graphics Card: Minimum of 2 GBs of dedicated RAM and OpenGL 3.3 or later
- Ports: USB